

Public information according to § 8a Hazardous Incident (Reporting) Ordinance /12. BImSchV

1. Name and location of the company

Operator in Germany: Ferro GmbH, Gutleutstraße 215, 60 327 Frankfurt, Germany

Local branch: Ferro GmbH Werk Magmalor Colditz, Furtweg 23, 04680 Colditz, Germany

2. Permit of the local branch by the relevant authorities

The Ferro Magmalor GmbH in Colditz is a company which faces the Hazardous Incident Ordinance / German Major Accidents Ordinance of the lower / basic class (before: basic duties). Relevant authority: Sächsischen Landesamt für Umwelt, Landwirtschaft und Geologie (LfULG), Referat 52, Söbringener Str. 3 a in 01326 Dresden-Pillnitz, Germany according to § 7 der 12. Bundesimmissionsschutzverordnung (12. BImSchV – Hazardous Incident Ordinance / German Major Accidents Ordinance) notified 11. July 2017.

3. Operations at the local site

Manufacturing of ceramic materials. Manufacturing of pigments and decoration materials with mixing-, calcining-, grinding-processes. The storage of the raw materials, intermediates, and end products is in bags, drums, IBC's and storage tanks.

4. Description of the relevant hazardous materials

E environmentally hazardous

E1 Acute and chronic hazards to the aquatic environment, category 1

E2 Chronic hazards to the aquatic environment, category 2

H2 Acute toxicity (oral, dermal, inhalation), category 2

P5c Flammable liquids

P8 Oxidizing liquids

5. General information in case of an relevant, where to get informations

In case of a fire there in an automatic alert to the local fire fighters of the town Colditz. In case of a relevant incident the local authorities will be informed. Please listen to the

announcements of the Police and Fire Fighters in case of an incident and possible announcements in the Radio and TV.

6. Date of the last inspection by authorities and where to get information

Last site inspection by authorities: 15.September 2022.

Next inspection: 2025

More information available at the LfULG Dresden:

<https://www.anlagensicherheit.sachsen.de/regelinspektionen-4015.html>

7. Where to get more detailed informations according to article 5 directive 2003/4/EG

More informations are available at the Sächsischen Landesamt für Umwelt, Landwirtschaft und Geologie (LfULG), Referat 52, Söbringener Str. 3 a in 01326 Dresden-Pillnitz, Phone +49 351 2612 5210, Fax +49 351 2612 5099.

Contact Ferro GmbH, Tel. +49 69 27116 0

Last update: 07.11.2022